

State of Utah

Department of Natural Resources

MICHAEL R. STYLER
Executive Director

Division of Oil, Gas & Mining

JOHN R. BAZA
Division Director

JON M. HUNTSMAN, JR. Governor

GARY R. HERBERT Lieutenant Governor

| Representatives Present During the Inspection: | | |
|--|--|--|
| OGM | Priscilla Burton Environmental Scientist III | |
| OGM | Steve Demczak Environmental Scientist III | |
| Company | Russell Hardy | |

Inspection Report

| Permit Number: | C0150007 | | |
|------------------|------------------------------|--|--|
| Inspection Type: | PARTIAL | | |
| Inspection Date: | Wednesday, October 12, 2005 | | |
| Start Date/Time: | 10/12/2005 12:30:00 PM | | |
| End Date/Time: | 10/12/2005 2:30:00 PM | | |
| Last Inspection: | Thursday, September 22, 2005 | | |

Inspector: Priscilla Burton, Environmental Scientist III

Weather: sun 65 F

InspectionID Report Number: 760

Types of Operations

Reprocessing

Accepted by: whedberg 11/7/2005

Permitee: CONSOLIDATION COAL CO

Operator: CONSOLIDATION COAL CO MID-CONTINENT REGION

Mineral Ownership

Other

Site: **HIDDEN VALLEY MINE**

Address: PO BOX 566, SESSER IL 62884

County: **EMERY**

Permit Type: PERMANENT COAL PROGRAM

Permit Status: **RECLAIMED**

Current Acreages

| Total Permitted | 960.00 |
|-----------------|--------|
| Total Disturbed | 6.70 |
| Phase I | 6.70 |
| Phase II | |
| Phase III | |

| | 71 |
|-----------|-------------|
| ☐ Federal | Underground |
| State | Surface |
| ☐ County | Loadout |
| ✓ Fee | Processing |

Report summary and status for pending enforcement actions, permit conditions, Division Orders, and amendments:

Sediment control at the site is functional, noted one silt fence needing adjustment.

| Inspect | tor's | Signa | ture |
|---------|-------|-------|------|
|---------|-------|-------|------|

Date

Friday, October 14, 2005

Priscilla Burton, Environmental Scientist III

Inspector ID Number: 37

Note: This inspection report does not constitute an affidavit of compliance with the regulatory program of the Division of Oil, Gas and Mining.

Permit Number: C0150007 Inspection Type: PARTIAL

Inspection Date: Wednesday, October 12, 2005

Page 2 of 3

REVIEW OF PERMIT, PERFORMANCE STANDARDS PERMIT CONDITION REQUIREMENTS

- 1. Substantiate the elements on this inspection by checking the appropriate performance standard.
 a. For COMPLETE inspections provide narrative justification for any elements not fully inspected unless element is not appropriate to the site, in which case check Not Applicable. b. For PARTIAL inspections check only the elements evaluated.
- 2. Document any noncompliance situation by reference the NOV issued at the appropriate performance standard listed below.
- Reference any narratives written in conjunction with this inspection at the appropriate performace standard listed below.
 Provide a brief status report for all pending enforcement actions, permit conditions, Divison Orders, and amendments.

| | | Evaluated | Not Applicable | Comment | Enforcement |
|------|---|-----------|----------------|----------|-------------|
| 1. | Permits, Change, Transfer, Renewal, Sale | | | | |
| 2. | Signs and Markers | | | | |
| 3. | Topsoil | | | | |
| 4.a | Hydrologic Balance: Diversions | ~ | | ✓ | |
| 4.b | Hydrologic Balance: Sediment Ponds and Impoundments | | | | |
| 4.c | Hydrologic Balance: Other Sediment Control Measures | ~ | | ✓ | |
| 4.d | Hydrologic Balance: Water Monitoring | ~ | | ✓ | |
| 4.e | Hydrologic Balance: Effluent Limitations | | | | |
| 5. | Explosives | | | | |
| 6. | Disposal of Excess Spoil, Fills, Benches | | | | |
| 7. | Coal Mine Waste, Refuse Piles, Impoundments | | | | |
| 8. | Noncoal Waste | | | | |
| 9. | Protection of Fish, Wildlife and Related Environmental Issues | | | | |
| 10. | Slides and Other Damage | | | | |
| 11. | Contemporaneous Reclamation | | | | |
| 12. | Backfilling And Grading | | | | |
| 13. | Revegetation | | | | |
| 14. | Subsidence Control | | | | |
| 15. | Cessation of Operations | | | | |
| 16.8 | a Roads: Construction, Maintenance, Surfacing | | | | |
| 16. | o Roads: Drainage Controls | | | | |
| 17. | Other Transportation Facilities | | | | |
| 18. | Support Facilities, Utility Installations | | | | |
| 19. | AVS Check | | | | |
| 20. | Air Quality Permit | | | | |
| 21. | Bonding and Insurance | | | | |
| 22. | Other | | | | |

Permit Number: C0150007 Inspection Type: PARTIAL

Inspection Date: Wednesday, October 12, 2005

Page 3 of 3

4.a Hydrologic Balance: Diversions

UD-1 in good shape. Dry.

4.c Hydrologic Balance: Other Sediment Control Measures

Silt fences and other drainage controls are functioning. One silt fence at base of Seam A has drooped and will be tightened.

4.d Hydrologic Balance: Water Monitoring

Water monitoring conducted in September as per plan. Photo of Ivie Creek attached.

